

## SURVEYOR'S CERTIFICATION

OHIO VALLEY GROUP, INC.

UNAUTHORIZED COPIES OF THIS PLAT OF SURVEY, NOR FOR ANY USE, OR RELIANCE UPON, BY PERSONS OTHER THAN THOSE SPECIFICALLY NAMED HEREIN FOR THE



This plat was prepared by D.B. Kosie & Associates Professional Land Surveying

www.dbksurveys.com

STATE CERTIFICATE OF AUTHORIZATION NO. 02946

11040 Madison Road Montville, Ohio 44064

440.286.2131

REGISTERED PROFESSIONAL LAND SURVEYOR REGISTRATION NO. 8167

DBK PLAT NO. 867-2 2014, 1094-1 2019

NOVEMBER

2014, 2019

SEPTEMBER THRU OCTOBER, 2014 SEPTEMBER THRU NOVEMBER, 2019

2014, 2019 CONTOUR AND MORPHOLOGY SURVEY OF


## THE EMERGENT WETLANDS AREA OF SLIP 5A PENINSULA AS SHOWN ON PLATE 6 OF THE SLIP 5A RESTORATION DESIGN DRAWING SET 2 PLAN OHIO VALLEY, INC. RAILROAD RESTORATION PROJECT - SLIP 5A

SEPTEMBER THE EASTERLY BANK OF THE ASHTABULA RIVER AT ASHTABULA HARBOR IN THE NOVEMBER CITY OF ASHTABULA, OHIO ORIGINAL ASHTABULA TOWNSHIP LOT NO. 7.
RANGE 3, TOWNSHIP 13 OF THE CONNECTICUT
WESTERN RESERVE OHIO VALLEY GROUP, INC.

REVISED: SEPTEMBER 24TH, 2014 REVISED: NOVEMBER 25TH, 2014 LAST REVISED: NOVEMBER 11TH, 2019

SEPTEMBER THRU OCTOBER, 2014 SEPTEMBER THRU NOVEMBER, 2019

SEE PAGE 1 OF 2 FOR PLAN VIEW







GROUND SHOT ELÉVATION OBSERVATION TIME: 30 SEC. PER/PT. MEAN WATER GAUGE OBSERVATION TIME: 120 SEC.
MEAN WATER ELEVATION OBSERVATION TIME: 300 SEC.

## **OBSERVATION DATE INFORMATION**

SECOND OBSERVATION (BLUE): SEPTEMBER 20TH, 25TH AND 26TH, 2019









DBK PLAT NO. 867-2 2014, 1094-2 2019

SEE PAGE NO. 1 OF 2 FOR SURVEYOR'S CERTIFICATION

